



California Medical Device Recall Information



Recall Name

Cook Medical Recalls Roadrunner Uniglide Hydrophilic Wire Guides Due to Potential Contamination with Glass Particles

Recall Date	Product Description	Recalling Firm	Recall Reason
06/24/16	Roadrunner Uniglide Hydrophilic Wire Guides	Cook Incorporated Bloomington, IN	<i>Contamination with glass particles.</i>
Recall Class	Product Identification	Distribution	Affected Dates
I	Click here for a list of affected product.	CA , nationwide	Distributed between: May 2, 2016 and June 17, 2016

FOR ADDITIONAL INFORMATION, PLEASE VISIT:

<http://www.fda.gov/MedicalDevices/Safety/ListofRecalls/ucm519224.htm>